



केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

Speed Post

January 17, 2018

CPCB-B 33014/187 (D) /2017/IPC-II 16290

To

M/s. SBQ Steel Ltd.
Ankalapaturu Vill, Chillakuru Mandal,
SPSR Nellore District
Andhra Pradesh

Sub: Inspection carried out to M/s. SBQ Steel Ltd. Ankalapaturu vill, Chillakuru Mandal, SPSR Nellore District, Andhra Pradesh w.r.t. OCEMS related non-compliance i.e. staying offline for more than one year.

Ref: Industry letter to CPCB, RD-Bangalore vide Ref. No. SBQ/CPCB/OPS/STOP/2017, dated 20.12.2017 regarding non-operational status.

Sir,

Please refer to your letter date 20.12.2017, to CPCB, RD- Bangalore, informing that due to no power demand, poor steel market and mounting losses the production process of entire unit was suspended from 14.11.2017.

It is to inform you that, your unit was to be inspected during December, 2017 for verification of compliance of norms, as a large number of OCEMS alerts have been generated in the previous month but the inspection in operating condition could not be carried out due to above reason. Therefore, you are required to not resume production without prior intimation to CPCB and ensure continuous data transmission from online emission and effluent monitoring systems of all required processes as per CPCB guideline to CPCB.

Yours Faithfully,

[Nazimuddin]

Div. Head, IPC-II

Copy to:

1. **The Chairman** For information please.
A P Pollution Control Board
Paryavarana Bhavan
A-III, Industrial Estate, Sanath Nagar
Hyderabad - 500018
2. **The Regional Director (South)** For information please.
Central Pollution Control Board
1st & 2nd Floors, Nisarga Bhavan,
A-Block, Thimmaiah Main Road,
7th D Cross, Shivanagar,
(Opp. Pushpanjali Theatre)
Bengaluru-560010 (Karnataka)
3. **The Divisional Head IPC-VI, Division,**
CPCB, Delhi
4. **The Divisional Head, IT Div.**
CPCB, Delhi